## **CAS Program Requirements for QP 1 For Every 2 Non-Certified Craftworkers North America Option A** Option B • 2-CAS L2 certified craftworkers • 1-CAS L2 certified craftworker and • 1-C7 or 1-C12 certified craftworker For Every 2 Non-Certified Craftworkers Globally Global **Option A or B Option C Option D** (Above) • 1-C7 and 1-C12 2-C7 or 2-C12 certified certified craftworker craftworkers **CAS Parallel Path Architecture** Path 1 Path 2 Level 1 Level 1 **Basic Coating Applicator** C-7 Blaster C-12 Blaster Pass Theory exam • 800 hours work • 800 hours work experience experience Theory exam Theory exam Practical exam Practical exam Level 2 Level 2 **Certified Applicator Specialist** • 6000 hours work experience Theory exam **Certified Applicator Specialist** Practical exam Valid C7 and C12 • 6000 hours work experience Theory exam

**AMPP**