# Aruba Instant On Release

**Notes** 



#### **Copyright Information**

© Copyright 2020 Hewlett Packard Enterprise Development LP.

#### **Open Source Code**

This product includes code licensed under the GNU General Public License, the GNU Lesser General Public License, and/or certain other open source licenses. A complete machine-readable copy of the source code corresponding to such code is available upon request. This offer is valid to anyone in receipt of this information and shall expire three years following the date of the final distribution of this product version by Hewlett Packard Enterprise Company. To obtain such source code, send a check or money order in the amount of US \$10.00 to:

Hewlett Packard Enterprise Company 6280 America Center Drive San Jose, CA 95002 USA

## **Revision History**

The following table provides the revision history of this document.

 Table 1: Revision History

Revision	Change Description	
Revision 12	<b>05-27-2020</b> : The Aruba Instant On mobile app version 2.0.0 introduces support for Aruba Instant On Switches.	
Revision 11	<b>05-09-2020</b> : The Aruba Instant On software version 2.0.1 was released.	
Revision 10	<b>05-04-2020</b> : The Aruba Instant On mobile app version 2.0.0 and software version 2.0.0 was released.	
Revision 09	<b>03-02-2020</b> : The Aruba Instant On software version 1.4.1 was released.	
Revision 08	<b>01-31-2020</b> : The Aruba Instant On mobile app version 1.4.0 and software version 1.4.0 was released.	
Revision 07	<b>12-16-2019</b> : The Aruba Instant On mobile app version 1.3.2 was released.	
Revision 06	12-03-2019: The Aruba Instant On software version 1.3.1 was released.	
Revision 05	11-14-2019: The Aruba Instant On mobile app version 1.3.1 was released.	
Revision 04	<b>11-01-2019</b> : The Aruba Instant On mobile app version 1.3.0 and software version 1.3.0 was released.	
Revision 03	<b>09-06-2019</b> : The Aruba Instant On mobile app version 1.2.1 was released.	
Revision 02	<b>08-23-2019</b> : The Aruba Instant On mobile app version 1.2.0 and software version 1.2.0 was released.	
Revision 01	07-30-2019: The Aruba Instant On software version 1.1.1 was released.	

### **Contacting Support**

**Table 2:** Contact Information

Main Site	arubainstanton.com
Support Site	support.arubainstanton.com
Instant On Social Forums and Knowledge Base	community.arubainstanton.com
North American Telephone	1-800-943-4526 (Toll Free) 1-408-754-1200
International Telephone	community.arubainstanton.com/t5/Contact-Support/ct- p/contact-support
EULA	https://www.arubainstanton.com/eula/
Security Incident Response Team	Site: arubanetworks.com/support-services/security-bulletins/ Email: aruba-sirt@hpe.com

#### **Related Documents**

The following guides are part of the complete documentation for the Aruba Instant On solution:

- <u>AP Installation Guides</u>
- Aruba Instant On User Guide
- Aruba Instant On Online Help Center

#### **Release Overview**

This release note covers Aruba Instant On application software, mobile app, and web application for the management of Instant On Access Points (APs) and switches. For more information on our current product offerings, visit the <u>Aruba Instant On website</u>.

The web version of the Aruba Instant On portal can be accessed at <u>portal.arubainstanton.com</u>.

# New Features and Enhancements Introduced in Instant On Releases

The following section lists the features and enhancements introduced in the different Aruba Instant On software, mobile app, and web application releases.

#### Version 2.0.1

This version includes the following:

- Aruba Instant On AP software version 2.0.1.
- Fixed the DLNA and Amazon TV compatibility issue.
- Other bugs fixes and stability improvements.

#### Version 2.0.0

This version includes the following:

- Aruba Instant On AP software version 2.0.0.
- Aruba Instant On Switch software version 1.0.1.
- Ability to configure and monitor Instant On 1930 Series switches.



Aruba Instant On 1930 Series switches will be available to order on June 1st 2020.

- Ability to add Instant On switches to a new or any existing site.
- Automatic synchronization of wired networks across Instant On devices.
- Quick view of port statuses and wired clients activity.
- Additional switch configurations, such as, Rapid spanning tree, 802.1X authentication, and Link aggregation.
- Ability to edit and rename any wired or wireless client for better identification.
- Allow full or limited access to specific network destinations for wireless clients.
- Ability to access and share typical multicast services, such as, printing, sharing and casting across networks.
- Simplified preferred partner integration with Aislelabs, Purple, Skyfii, and Wavespot for easy guest portal setup and comprehensive analytics.
- Better control over software updates to install them immediately or delay them by an additional week.

#### Version 1.4.1

This version includes the following:

Bug fixes and stability improvements.

#### Version 1.4.0

This version includes the following:

- Support for PPPoE connectivity in Wi-Fi router mode.
- Ability to view and block applications per network.
- Ability to view top used applications per client.
- Simplified configuration of RADIUS Network Access Attributes and NAS IP Address.
- Support for Open Guest network security.
- Ability to control Wi-Fi band selection (2.4GHz and 5GHz) for wireless networks.
- Ability to enable or disable legacy 802.11b rates.
- Radio channel selection improvements and ability to control channel selection and channel width.
- Ability to turn device LED off when operating under normal conditions.
- Ability to disable application visibility engine for performance sensitive deployments.
- Improved wireless range for over-the-air connections and better support of outdoor deployments.
- Wireless client roaming performance improvements.
- Other minor bug fixes and usability enhancements.

#### Version 1.3.2

This version includes the following:

Bugs fixes and stability improvements.

#### Version 1.3.1

This version includes the following:

- Improvements made to select the best Instant On AP for over-the-air connection.
- Fixed wireless network not being broadcast on the 5 GHz radio for Israel, Japan, and Egypt.
- Bug fixes and stability improvements.

#### Version 1.3.0

This version includes the following:

- Support for the Aruba Instant On mobile app and web application in two new languages Korean and Traditional Chinese.
- Possibility to block specific application categories on a network.
- Instant On devices can now be deployed as a Wi-Fi router to the Internet when it connects directly to a modem.
- Additional help and troubleshooting information is included during the initial setup of a site.
- Additional visibility and monitoring information over device connectivity and Ethernet port activity.
- New options added in the Guest Portal Facebook Wi-Fi, third-party External Captive Portal integration).
- Instant On APs add their names in DHCP requests, allowing easier management of the network infrastructure.

#### Version 1.2.1

This version includes the following:

Bugs fixes and stability improvements.

#### Version 1.2.0

This version includes the following:

- Multi-language support in the following languages for the Instant On mobile app and web application and also the Online Help.
  - English
  - Chinese (Simplified)
  - French
  - German
  - Italian
  - Japanese
  - Portuguese
  - Spanish (Latin America)
- Possibility to block specific wireless clients from accessing the network.
- Ability to limit client bandwidth usage on the network.
- Internal DHCP for clients on employee networks
- Bugs fixes and stability improvements.

#### Version 1.1.1

This version includes the following:

- 802.11r support and performance improvements when roaming between APs.
- Support for Aruba Instant On AP-17 access points.
- Bug fixes and stability improvement.

#### **Known Issues**

This section describes the known issues observed in Aruba Instant On 2.0.1.

Table 3: Known Issue in Instant On 2.0.1

Bug ID	Description
SMB-2450	When an application category is being blocked, clients currently using the application may still be allowed access until their session expires.
SMB-3459	Sonos speakers may not be available, when casting music from streaming apps.
SMB-4078	When multiple Instant On devices detect the same client, the client appears in the client list for each device reporting it.